

LAX Airport Operations LAX Operations Advisory

Bulletin No: 2017-13 (revised)

Ramp Control and Gate Management Changes

In addition to the airline relocations currently underway, there will also be some changes occurring to Ramp Control and Gate Management. Please see the matrix below indicating the Ramp Tower changes in red that will go into effect on Wednesday, May 17th, 2017 at 2am.

TAXILANE	OPERATOR	FREQUENCY	EFFECTIVE DATE	EFFECTIVE TIME	OPERATING HOURS
C6	United	129.5	No change	No change	0600 - 2300
C7	United	129.4	No change	No change	0600 - 2300
C8	Alaska	130.85	05/17/2017	0200	0500 - midnight
C9	American	130.5	05/17/2017	0200	0530 - 2230
C10	American	129.325	No change	No change	0645 - 2330
D7	ATC	121.65	No change	No change	24/7
D8	ATC	121.65	No change	No change	24/7
D9	Delta	131.45	05/17/2017	0200	24/7
D10	ATC	Ground	No change	No change	24/7

In addition to the changes for ramp control, gate management responsibilities will transition to TBITEC (424 646-9938) for Terminal 5 gates and to LAX6 (310 258-8360) for Terminal 6 Gates. These transitions will also occur on Wednesday, May 17th 2017 at 2am and will be available 24/7.

For questions or comments regarding this advisory please contact Airside Manager, Jeff Mort, <u>Jmort@lawa.org</u>.

Issue Date: May 16, 2017

Subject: Ramp Control and Gate Management Changes

*The LAX Operations Advisory will be posted on LAWA's Airport Operations

web site and can be retrieved at http://www.lawa.org/airops.aspx

